



**RESUME WORK
IN THE MATTER OF THE NATIONAL ENERGY BOARD ACT,
FOLLOWING AN ORDER UNDER SECTION 51.1**

On 28 August 2014, the undersigned National Energy Board Inspection Officer hereby
Date/time

notifies [REDACTED], Enbridge Pipelines Inc. that the hazardous or detrimental situation
Company Representative and company name

described in Order No. DWL-001-2014 has been remedied to the satisfaction of the Inspection Officer.
Inspection Officer order

Therefore, Suspended work may resume, and/or

the measures specified in the order have been satisfied.

| | | | |
|--|----------------|------------------|------------|
| Inspection Officer | [REDACTED] | [REDACTED] | [REDACTED] |
| | Name | IO Designation # | Telephone |
| | 28 August 2014 | Signature | |
| | Date | | |
| Centre 10 – 517, 10th Avenue SW Calgary AB T2R 0A8 | | | |